



S.A. 31T-5

Modification FAA DOA EA-1 Approved

December 3, 1981

To: All Piper CORPAC's
Attention: CORPAC Service Administrator
Subject: Oxygen Control Cable Installation Modification
Model Affected: PA-31T2 Cheyenne II XL
Serial Numbers Affected: 31T-8166005 through 31T-8166012

Compliance Time: Within the next fifty (50) hours of operation or at the next scheduled inspection event, whichever occurs first.

Purpose: It has been determined that in the above-listed aircraft, the oxygen system control (ON/OFF) cables may be installed in such a manner that moisture could enter and accumulate between the cable core and housing. In freezing temperatures, this condition could render the oxygen control system inoperable.

This Service Release announces the availability of a kit containing instructions and material for modification and repositioning of the cable to keep moisture out of the cable housing.

Material Required: One (1) each per aircraft, Oxygen System Control Cable Modification Kit, Piper Part Number 764 259.

Effectivity Date: This Service Release is effective upon receipt.

Summary: Please advise current owner/operator of affected aircraft in your area to arrange for compliance in accordance with Compliance Time, above. Identify aircraft by serial number when ordering kit.

Credit is available for all material and for up to three (3) hours labor, provided confirmation of compliance with this Service Release is received within sixty (60) days of the date of this release. Comply with Product Condition/Compliance Report procedure.