



Piper Aircraft Corporation
Vero Beach, Florida, U.S.A.

SERVICE *No. 836A* BULLETIN

* PIPER CONSIDERS *
* COMPLIANCE MANDATORY *

August 26, 1986

S/M

FAA Approved

Date

(Service Bulletin No. 836A supersedes and voids Service Bulletin No. 836, dated May 21, 1986)

SUBJECT:

Aluminum Wire Inspection/Replacement

REASON FOR REVISION:

To correct Serial Numbers Affected
and Revise Instructions.

MODELS AFFECTED:

SERIAL NUMBERS AFFECTED:

E-2/J-2 Series Cub
J-3, NE-1, L-4 Series Cub
J-4 Series Coupe
J-5, J-5C, L-14, AE-1, HE-1 Series
Cub Cruiser
PA-11 Cub Special
PA-12 Super Cruiser
PA-14 Family Cruiser
PA-15 Vagabond
PA-16 Clipper
PA-17 Vagabond
PA-18 Super Cub
PA-19 Pacer
PA-20 Pacer
PA-22 Tripacer/Colt
PA-23-150/160 Apache
PA-23-235 Aztec
PA-23-250 Aztec
PA-24-180/250 Comanche
PA-24-260 Comanche
PA-24-400 Comanche
PA-25-150 Pawnee
PA-25-235 Pawnee
PA-25-260 Pawnee
PA-28-140 Cherokee
PA-28-150/160 Cherokee
PA-28-151 Warrior
PA-28-161 Warrior II
PA-28-180 Cherokee
PA-28R-180 Arrow
PA-28-181 Archer II

A11
A11
A11

5-01 through 5-1389
11-01 through 11-1678
12-01 through 12-4036
14-01 through 14-523
15-01 through 15-388
16-01 through 16-736
17-01 through 17-215
18-01 through 18-8309025
19-01 through 19-03
20-01 through 20-1121
22-01 through 22-9848
23-01 through 23-2046
27-505 through 27-622
27-01 through 27-7954121
24-01 through 24-3687
24-3642 through 24-6000
26-01 through 26-148
25-01 through 25-731
25-2000 through 25-8056038
25-4415 through 25-8156024
28-20001 through 28-7725290
28-01 through 28-4377
28-7415001 through 28-7715314
28-7716001 through 28-8216226
28-671 through 28-7505259 and 28-E13
28R-30001 through 28R-7130013
28-7690001 through 28-8290061

(over)
ATA: 2400

MODELS AFFECTED: (Cont'd)

PA-28R-200 Arrow/Arrow II
PA-28R-201 Arrow III
PA-28-201T Turbo Dakota
PA-28R-201T Turbo Arrow III
PA-28RT-201 Arrow IV
PA-28RT-201T Turbo Arrow IV
PA-28-235 Cherokee
PA-28-236 Dakota
PA-30 Comanche
PA-31-300 Navajo
PA-31-310 Navajo
PA-31-325 Navajo
PA-31-350 Navajo Chieftain
PA-31P Pressurized Navajo
PA-31T Cheyenne/Cheyenne II
PA-31T1 Cheyenne I
PA-32-301T Turbo Saratoga
PA-34-200 Seneca I
PA-34-200T Seneca II
PA-34-220T Seneca III
PA-36-285 Brave
PA-36-300 Brave
PA-36-375 Brave
PA-38-112 Tomahawk
PA-39 Twin Comanche
PA-44-180 Seminole
PA-44-180T Turbo Seminole

SERIAL NUMBERS AFFECTED: (Cont'd)

28R-35001 through 28R-7635545
28R-7737001 through 28R-7837317
28-7921001 through 28-7921091
28R-7703001 through 28R-7803372
28R-7918001 through 28R-8118082
28R-7931001 through 28R-8131192
28-10001 through 28-7710089 and 28-E11
28-7911001 through 28-8211013
30-02 through 30-2000
31-228 through 31-511
31-05 through 31-8012070
31-7400990 through 31-8012070
31-5001 through 31-8052153
31P-03 through 31P-7730012
31-7400001 through 31-7920094
31-7804002 through 31-7904057
32-8024001 only
34-7250001 through 34-7450220
34-7570001 through 34-8170092
34-8133001 through 34-8233205
36-7360001 through 36-7660135
36-7760001 through 36-7960078
36-7802001 through 36-7902051
38-78A0001 through 38-82A0122
39-01 through 39-155
44-7995001 through 44-8195026
44-8107001 through 44-8207020

COMPLIANCE TIME:

At the next regularly scheduled inspection event, but not to exceed fifty (50) hours of operation.

PURPOSE:

Field reports have been received of corrosion between the aluminum terminal and aluminum wire at the battery positive post, resulting in overheating of the wire due to high electrical resistance. If this condition exists and is left uncorrected, excessive heat build-up could result in an electrical fire. Corrosion and resulting high resistance can also occur in the battery to ground, battery to master relay, master relay to starter solenoid, starter solenoid to starter and engine return ground cables.

INSTRUCTIONS:

1. On each affected aircraft, locate and identify the following cables:

- A. Battery to ground
- B. Battery to master relay
- C. Master relay to starter solenoid
- D. Starter solenoid to starter
- E. Engine return ground cable (engine to airframe)

INSTRUCTIONS: (Cont'd.)

2. Inspect the cables listed above for the presence of aluminum wire.
3. If aluminum wire is found, replace the affected cable(s) with copper cable(s).

NOTE: Replacement cables for AL-1 wire shall be fabricated of AN-4 copper wire; for AL-00 wire, fabricate from AN-2 copper wire, using copper wire listed below, all wire recommended is of 150 C. rating.

Copper Wire

Mil-W-22759/4	Mil-W-22759/41
Mil-W-22759/8	Mil-W-81044/5
Mil-W-22759/13	Mil-W-81044/6
Mil-W-22759/16	Mil-W-81044/8
Mil-W-22759/34	Mil-W-81044/9

Use appropriate terminals listed below or equivalent.

<u>AN-2</u>	<u>AMP</u>	<u>AMP</u>	<u>Mil. Spec.</u>
1/4	51982	320383	MS20659-113
1/4	51982-1	322870	MS20659-147
5/16	51982-2	321600	MS20659-114
1/4	324034	-	MS20659-113 Requires 90° bend
3/8	35249	-	MS20659-114 Requires 90° bend
3/8	321600	-	MS20659-114
1/2	51982-3	321602	MS20659-133

<u>AN-4</u>	<u>AMP</u>	<u>AMP</u>	<u>Mil. Spec.</u>
1/4	321671	-	MS25036-123
5/16	322010	-	MS25036-124
3/8	322898	-	MS25036-125 Requires 90° bend
3/8	322011	-	MS25036-125
1/4	33469	-	MS20659-111
5/16	33470	-	MS20659-132
3/8	33471	-	MS20659-112
3/8	324102	-	MS25036-125 Requires 90° bend
3/8	321121	-	MS25189-115

CAUTION: Use of proper crimping tool for copper cable/terminal combination utilized is required.

MATERIAL REQUIRED:

To be determined by inspection.

(over)

AVAILABILITY OF PARTS:

Your Piper Field Service Facility or local procurement.

EFFECTIVITY DATE:

This Service Bulletin is effective upon receipt.

SUMMARY:

Please contact your Piper Field Service Facility to arrange for compliance with this Service Bulletin in accordance with Compliance Time indicated.

NOTE: If you are no longer in possession of this aircraft, please forward this information to the present owner.