

# SERVICE



# LETTER

Service Letter No. 241

January 24, 1955

TO: All Distributors, Dealers, Owners and Operators

SUBJECT: 1955 PA-22 Cigarette Lighters

MODELS AFFECTED: All 1955 Models

It has been brought to our attention that in a few of the 1955 Models the cigarette lighter will pop out of its socket when it has become fully heated.

A thorough investigation has been made, and it was found that there was a slight variation in the size of the cigarette lighter socket, and a few of the 1955 Model PA-22's were delivered with a small lighter in the larger socket.

It is requested that your cigarette lighter be checked, and if it does not remain firmly engaged after the initial heating, the complete lighter assembly (lighter and socket) should be removed from the panel and returned to the Service Department of Piper Aircraft Corporation, Lock Haven, Pennsylvania, for replacement.

Very truly yours,

PIPER AIRCRAFT CORPORATION

Rolland Boardman  
Service Manager

RB:mh

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.