



S.A. 31T-2
June 25, 1981

Modification FAA DOA EA-1 Approved

To: All Piper CORPAC's

Attention: CORPAC Service Administrator

Subject: Listing of Starter/Generator Installations in
Pilot's Operating Handbook (Report: 2210 or
Report: 2230) Equipment List

Models Affected: PA-31T Cheyenne II

Serial Numbers Affected: 31T-8120001 through 31T-8120010,
31T-8120020 through 31T-8120029

Compliance Time: At earliest opportunity; not to exceed next
scheduled maintenance event.

Purpose:
To insure that the Starter/Generators installed in the above-listed airplanes are
appropriately identified in the Equipment List of the Pilot's Operating Handbook.

Instructions:

1. In Section 6, Weight and Balance, of the Pilot's Operating Handbook locate
Item No. 71 in the Electrical Equipment section of the Equipment List.
2. For aircraft with Serial Numbers 31T-8120001 through 31T-8120010,
31T-8120021, 31T-8120022, 31T-8120024 through 31T-8120029, use opaque
typing correction fluid or eraser to delete "X" marked for Lear-Siegler
installations. Mark "X" to designate Auxelec installations.
3. Aircraft Serial Numbers 31T-8120020 and 31T-8120023 each have one
Lear-Siegler and one Auxelec Starter/Generator installed. One of each must
be marked "X".
4. Make logbook entry of compliance with this Service Release.

Material Required:
Not Applicable.

(over)

Availability of Parts:

Not Applicable.

Effectivity Date:

This Service Release is effective upon receipt.

Summary:

Please advise current owner/operator of affected aircraft to arrange for compliance with this Service Release in accordance with Compliance Time, above.