



NOTES:

1. FOR ENGINE SPEEDS BELOW 1000 RPM, SOME NEEDLE AGITATION MAY BE OBSERVED IN TACHOMETER READING DUE TO VERY SLOW SIGNAL RATE FROM IGNITION SYSTEM.
2. WITH THE ENGINE NOT RUNNING, A READING IN THE VICINITY OF 400 RPM IS NORMAL.

TITLE	PAGE
TACHOMETER 2X MULTIPLIER	2.4